

Producer	Model	InnCable		InnSmart	
		Compatible	Cable Type	Compatible	OS
Samsung	HG55AT690UK	YES	RJ12	YES	TIZEN
Samsung	HG43AT690UK	YES	RJ12	YES	TIZEN
Samsung	HG55AU800AW	YES	MiniJack - Both	YES	TIZEN
Samsung	G48AD690DW	YES	RJ12	NO	Orsay
Samsung	HG48AE690DK	YES	RJ12	NO	Orsay
Samsung	HG55BU800NF	YES	MiniJack - Both	YES	TIZEN
LG	55UR770H	YES	RJ12 (MPI, RS232)	YES	WebOS 5.0
Samsung	HG65AU800AWXXM	YES	MiniJack - Both	YES	TIZEN
Samsung	HG55AU800AWXXM	YES	MiniJack - Both	YES	TIZEN
LG	50UQ80006LD	NO	---	NO	WebOS
LG	55US660H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	43US660H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	55LV761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 3.5
LG	49LV761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 3.5
LG	43LV761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 3.5
LG	32LV761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 3.5
LG	65US761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0

LG	55US761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	49US761H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
Samsung	HG43AU800EE	YES	MiniJack - Both	YES	TIZEN
LG	43US660H0GD	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	50UM660H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	55LX774H-VA	YES	MiniJack - RJ12 MPI	NO	---
LG	65LX774H-VA	YES	MiniJack - RJ12 MPI	NO	---
Samsung	HG65ND890UFXZA	YES	MiniJack - RS-232C (RJ12)	NO	---
Samsung	HG55ND890UFXZA	YES	MiniJack - RS-232C (RJ12)	NO	---
LG	50US660H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
LG	55UR762H	YES	RJ12 (MPI, RS232)	YES	WebOS 5.0
LG	55UM777H	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	43UT570H	YES	RJ12 (MPI, RS232)	NO	---
LG	49UT570H	YES	RJ12 (MPI, RS232)	NO	---
LG	55UT570H	YES	RJ12 (MPI, RS232)	NO	---
LG	65UT570H	YES	RJ12 (MPI, RS232)	NO	---
Samsung	HG49NE477S	YES	RJ12 (Exist as alt. Ex-Link)	NO	---
Samsung	HG55NE477S	YES	RJ12 (Exist as alt. Ex-Link)	NO	---

LG	43UM660H	YES	Minijack - RS-232C (D-Sub 9 Pin)	YES	WebOS 5.0
Samsung	HG55AU800NF	YES	MiniJack - Both	YES	TIZEN
LG	43US670H9UA	YES	RS-232C - D-Sub 9 pin, MPI - RJ12	YES	WebOS 5.0
LG	50UR770H9UA	YES	RS-232C - D-Sub 9 pin, MPI - RJ12	YES	WebOS 5.0
LG	55UR770H9UA	YES	RS-232C - D-Sub 9 pin, MPI - RJ12	YES	WebOS 5.0
LG	65UR770H9UD	YES	RS-232C - D-Sub 9 pin, MPI - RJ12	YES	WebOS 5.0
LG	65UM777H	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	43UM670H0A	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	50UM670H0A	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	55UM670H0A	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	65UM670H0A	YES	RJ12 (MPI, RS232)	YES	WebOS2.3
LG	55UR760H9UA	YES	RJ12 (MPI, RS232)	YES	WebOS 5.0
LG	55UN570H0UA	YES	RJ12 (MPI, RS232)	NO	---
LG	65UR777H	YES	RJ12 (MPI, RS232)	YES	WebOS 6.0
LG	55UR777H	YES	RJ12 (MPI, RS232)	YES	WebOS 6.0
LG	50UR777H	YES	RJ12 (MPI, RS232)	YES	WebOS 6.0
Samsung	HG43ND470SFXZA	YES	RJ12	NO	---
LG	65UT770H0UB	YES	RJ12 (MPI, RS232)	YES	WebOS 4.5

LG	32LN560HBUA	YES	RJ12 (MPI, RS232)	YES	WebOS 22
Samsung	HG55CU700NFXZA	YES	MiniJack - Both	NO	Tizen 7

Revision #25
Created 2024-03-15 11:12:16 UTC by Guest
Updated 2025-12-12 14:18:16 UTC by Guest